

Pos.	Bulletin No	Ref. to Fact. Nos	Contents of Bulletin	Way of introducing	Remarks
1.	Bulletin No BK-001/72 "Cobra 15"	All gliders /1972/	Replacement of pages in Technical Description, Technical Service Manual, Schedule of Periodic Inspection /i.e. pages Fig. 13, Fig. 9, Fig. 32, and description of pages Fig. 32 and Fig. 33/	<u>Immediately</u>	
2.	Bulletin No BK-002/75 "Cobra 15"	All gliders up to Fact. No W-688 and glider W-690 /except of W-556/	Replacement of the special screw fitting of horizontal tailplane to its bracket fixing	<u>Immediately</u>	
3.	Bulletin No BE-002/75 "Foka-24C" "Foka-24-4A" „Foka-5" "Cobra 15"	Gliders having the wooden aileron only	Inspection of the aileron balancing weight fitting	At the nearest inspection after 100 flying hours	Joint Bulletin for SZD-24C, SZD-24-4A, SZD-32A, SZD-36A
4.	Bulletin No BR-003/77 "Cobra 15"	Gliders of Fact. Nos from W-744 to W-821 incl.	Replacement of air brake control lever	In operation	
5.	Bulletin No BR-004/80 "Cobra"	All gliders SZD-36 SZD-36A and SZD-39	Case of the longitudinal cracks on leading edge of horizontal tailplane or wing appearing on the gliders: SZD-36, SZD-36A and SZD-39	If the crack is large /deep/ <u>immediately</u> if the crack is small - when operation is broken	
6.	Bulletin No BE-005/36/81	All gliders SZD-36A "Cobra-15"	Extending the overhaul life of SZD-36A "Cobra 15" gliders	Obligatory from the date of Bulletin issued /March 8, 1982/	
7.	Bulletin No BI-006/83 "Cobra"	All gliders SZD-36, SZD-36A and SZD-39	List of Bulletins for SZD-36, SZD-36A and SZD-39 "Cobra" gliders issued till May 31, 1983.	For information only	