

LIST OF BULLETINS ISSUED UP TO DATE FOR SZD-36, SZD-36A, SZD-39 "COBRA"

Pos.	Bulletin No	Ref. to Fact. Nos	Contents of Bulletin	Way of introducing	Remarks
I	II	III	IV	V	VI
1.	Bulletin No BK-001/72 "Cobra 15"	All gliders /1972/	Replacement of pages in Technical Description, Technical Service Manual, Schedule of Periodic Inspection /i.e. pages Fig. 13, Fig. 9, Fig. 32, and description of pages Fig. 32 and Fig. 33/	<u>Immediately</u>	
2.	Bulletin No BK-002/75 "Cobra 15"	All gliders up to Fact. No W-688 and glider W-690 /except of W-556/	Replacement of the special screw fitting of horizontal tailplane to its bracket fixing	<u>Immediately</u>	
3.	Bulletin No BE-002/75 "Foka-24C" "Foka-24-4A" „Foka-5" "Cobra 15"	Gliders having the wooden aileron only	Inspection of the aileron balancing weight fitting	At the nearest inspection after 100 flying hours	Joint Bulletin for SZD-24C, SZD-24-4A, SZD-32A, SZD-36A
4.	Bulletin No BR-003/77 "Cobra 15"	Gliders of Fact. Nos from W-744 to W-821 incl.	Replacement of air brake control lever	In operation	
5.	Bulletin No BR-004/80 "Cobra"	All gliders SZD-36 SZD-36A and SZD-39	Case of the longitudinal cracks on leading edge of horizontal tailplane or wing appearing on the gliders: SZD-36, SZD-36A and SZD-39	If the crack is large /deep/ <u>immediately</u> if the crack is small - when operation is broken	
6.	Bulletin No BE-005/36/81	All gliders SZD-36A "Cobra-15"	Extending the overhaul life of SZD-36A "Cobra 15" gliders	Obligatory from the date of Bulletin issued /March 8, 1982/	
7.	Bulletin No BI-006/83 "Cobra"	All gliders SZD-36, SZD-36A and SZD-39	List of Bulletins for SZD-36, SZD-36A and SZD-39 "Cobra" gliders issued till May 31, 1983.	For information only	
8.	Bulletin No BE-007/94 "Cable tension members"	All SZD gliders	Standardization of servicing basic for cable tension members in all SZD gliders	Obligatory when this Bulletin is obtained, to make easier the servicing of gliders	