

Pos.	Bulletin No	Ref. to Fact. Nos	Contents of Bulletin	Way of introducing	Remarks
1.	Bulletin of changes No 10/SZD-24C /1962/	Gliders SZD-24C Foka type having S/N: W-144, W-146, W-147, W-148, W-151, W-153.	Control column replacement	To be introduced immediately after receipt this bulletin	ONLY POLISH AND GERMAN LANGUAGE VERSION
2.	Bulletin of changes No 12/SZD-24C /1962/	All SZD-24C gliders	Replacement of the rubber-covering in the aileron-slot, with a plywood-construction	Acc. to User's decision	
3.	Bulletin of changes No 35 SZD-24C Foka /German No 11/SZD- 24C/ /1961/	All SZD-24C Foka gliders up to W-162 incl.	Strengthening of fuselage back side	To be introduced immediately	ONLY POLISH AND GERMAN LANGUAGE VERSION
4.	Bulletin of changes No 43 SZD-24C Foka /German and English No 13/SZD-24C Foka/ /1964/	All SZD-24C Foka gliders	Ball-coupling nuts in flying controls	To be introduced during the operation	
5.	Bulletin of changes No 44 /1964/	All SZD-24C Foka gliders up to W-213 incl.	Front stabilizer fitting (fitting on the spar)	Acc. to User's decision	
6.	Bulletin of changes No 49 /German and English No 14/SZD-24C Foka/ /1964/	All SZD-24C Foka gliders	A. Two special quick-release aileron control drive fork connectors in fuselage. B. One special quick-release elevator control drive fork connector in fuselage	To be introduced immediately	
7.	Bulletin of changes No 54 /1965/	All SZD-24 A, B, C Foka and SZD-24-4A Foka 4 gliders	Pedals	To be introduce in main overhaul	
8.	Bulletin of changes No 57 /1967/	All 24C Foka gliders	Flight Manual	To be introduced immediately	
9.	Bulletin of changes No 59 /1967/	All SZD-24 A, B, C Foka and SZD-24-4A Foka 4 gliders having not introduced these changes	Emergency lock of the canopy opening	To be introduce in main overhaul or during the operation	

Actual status: 1st May 2008

Pos.	Bulletin No	Ref. to Fact. Nos	Contents of Bulletin	Way of introducing	Remarks
10.	Bulletin No BE-002/75 Foka 24-C Foka 24-4A Foka 5 Cobra 15	All Foka 24-C, Foka 24-4A, Foka 5 and Cobra 15 having the wooden ailerons	Inspection of the aileron balancing weight fittings	To be introduce in nearest overhaul	
11.	Bulletin No BE-004/72 Foka 4	All SZD-24-4A Foka 4 gliders produced for G.S.T.	Changing the conditions of gliders operation	Since the day 31.12.72	ONLY POLISH AND GERMAN LANGUAGE VERSION
12.	Bulletin No BR-005/75 Foka 4	All SZD-24-4A Foka 4 gliders	Introducing the Annex No 1 to Technical Service Manual concerning the extended range of glider periodic inspections		
13.	Bulletin No BE- 06/4A/80 Foka 4	All SZD-24-4A Foka 4 gliders	Changes of repair time periods and further operation		
14.	Bulletin No BI-007/83 Foka	All SZD-24 A, B, C Foka and SZD-24-4A Foka 4 gliders	Information about bulletins issued up to date 31.05.83		
15.	Bulletin No BE-008/85 Foka C	All SZD-24C Foka gliders	Unification and way of periodic inspections for SZD-24C Foka C gliders on base of the bulletin data for SZD-24- 4A Foka 4 type	Acc. to User's decision	