

Pos.	Bulletin No	Ref. to Fact. Nos	Contents of Bulletin	Way of introducing	Remarks
1.	BE-01/76 "JANTAR-1"	From B-608 to B-677 and also B-682.	Change of the flight limitations /limitation of max airspeed/.	Introduce at once.	Invalidated after introducing BK-02/76 "JANTAR-1"
2.	BK-02/76 "JANTAR-1"	B-608, from B-611 to B-613, from B-615 to B-627, from B-634 to B-679 and from B-682 to B-689.	Replacement of arbors and strengthening of the spar roots.		
3.	BS-03/78 SZD-38A "JANTAR-1"	All SZD-38A "JANTAR-1" gliders used by APRL.	Replacement of TOST hook with SZD-III.A 56 hook.	At User's need.	Bulletin has been elaborated for APRL
4.	-	-	-	-	Item used as BK-04/78 SZD-48 "Jantar Std 2"
5.	-	-	-	-	Item used as BE-05/78 SZD-41A "Jantar Std"
6.	-	-	-	-	Item used as BE-06/41A/79 SZD-41A "Jantar Std"
7.	BE-07/79 "JANTAR"	All below mentioned gliders: <u>SZD-37x, SZD-37, SZD-38, SZD-38A, SZD-41, SZD-41A, SZD-41B, SZD-42, SZD-42-1, SZD-42-2, SZD-48 and SZD-48-1.</u>	Lacquer removal from the spar root end, rood end and root rib, then painting with colourless lacquer.	Introduce during nearest pause in flying.	
8.	BE-08/79 "JANTAR"	All gliders: <u>SZD-37x, SZD-38, SZD-38A, SZD-42, SZD-42-1, SZD-42-2.</u>	Change of overhaul life time up to 1500 flying hours and inspections relevant to this.	After completing previous established flying hours of after 6 years of operation.	
9.	BR-09/80 "JANTAR"	All gliders: <u>SZD-37x, SZD-37, SZD-38, SZD-38A, SZD-41, SZD-41A, SZD-41B.</u>	Change of the control stick fixing in the housing /replacement of the tubular rivets with the screws/.	If the play appears - introduce at once.	
10.	BE-10/80 "JANTAR"	All types of gliders: <u>SZD-37x, SZD-37, SZD-38, SZD-38A, SZD-41, SZD-41A, SZD-41B.</u>	The inspected hole performing in the fin fairing for inspection of the elevator control lever-to-the control push-rod connection.	At User's need.	

Pos.	Bulletin No	Ref. to Fact. Nos	Contents of Bulletin	Way of introducing	Remarks
11.	BA-011/81 "JANTAR"	All types of gliders: <u>SZD-37x, SZD-37, SZD-38, SZD-38A, SZD-41, SZD-41A, SZD-41B, SZD-48, 48-1 and SZD-49.</u>	<ol style="list-style-type: none"> 1. Inspection of rudder lever fitting. 2. Replacement of the standard safety pin with the special safety pin securing the rudder. 3. Strengthening of the central rib in stabilizer. 4. Inspection of the elevator sandwich coverings condition. 	Introduce at once.	
12.	-	-	-	-	Item used as BK-012/81 "Jantar-2"
13.	BS-13/81 "JANTAR"	Following glider types: <u>SZD-37x, SZD-37, SZD-38, SZD-38A, SZD-41, SZD-41B</u> and SZD-42 property of APRL.	Conditional extension of introduction time of Bulletin No BE-08/79	At User's need Ref. only APRL.	Elaborated for APRL.
14.	BK-014/81 "JANTAR"	Glider types mentioned below: <u>SZD-37x, SZD-37, SZD-38, SZD-38A, SZD-41, SZD-41B</u> and SZD-41A up to serial No. B-817 incl.	Strengthening of the cuts in the stabilizer rear fitting by means of the steel stop improving mating between the fitting and the fixing stone.	If the play is excessive, Bulletin introduce at once.	
15.	BK-015/81 "JANTAR"	Glider types mentioned below: <u>SZD-37x, SZD-37, SZD-38, SZD-38A, SZD-41, 41A, 41B, SZD-42, 42-1, SZD-42-2</u> up to serial No. B-1126 incl., <u>SZD-48, SZD-48-1</u> up to serial No. B-1202 incl. and SZD-49.	Securing of the instrument panel cover against the unintentional shifting out of the fixing.	Introduce after receive Bulletin.	
16.	BR-016/81 "JANTAR"	Below listed glider types: <u>SZD-37, SZD-38, SZD-38A</u> (from Fact. No B-609 to B-627, from B-634 to B-642 and from B-664 to B-689), <u>SZD-42, 42-1, SZD-42-2, SZD-48 and SZD-48-1.</u>	Replacement of the bolts connecting the aileron control lever in wing with aileron.	The change described in the Bulletin shall be introduced up to 30 Sept. 1983.	
17.	BI-017/82 "JANTAR"	Below listed glider types: <u>SZD-37, SZD-38, SZD-38A, SZD-41, SZD-41A, SZD-41B, SZD-42, 42-1, SZD-42-2, SZD-48 and SZD-48-1.</u>	The list of issued Bulletins for Jantar gliders updated condition on day April 30, 1982	To be dealt as the information.	
18.	-	-	-	-	BA-018/83 "JANTAR 2B" concerns SZD-42-2 only.

Pos.	Bulletin No	Ref. to Fact. Nos	Contents of Bulletin	Way of introducing	Remarks
19.	BK-019/83 "JANTAR"	Below listed glider types: SZD-37x, SZD-38, SZD-38A, SZD-41, SZD-41A, SZD-41B, SZD-42, 42-1, SZD-42-2, SZD-48 and SZD-48-1.	Replacement of compensation volume fastening clamps in the instrument panel.	Bulletin recommended by the producer. The way of introducing is left for the user's decision.	
20.	-	-	-	-	BE-020/83 "JANTAR Std 3" concerns SZD-48-3 only.
21.	-	-	-	-	BE-021/84 "JANTAR Std 3" concerns SZD-48-3 only.
22.	-	-	-	-	BE-022/85 "JANTAR Std 3" concerns SZD-48-3 only.
23.	-	-	-	-	BE-023/85 "JANTAR Std" concerns SZD-48, SZD-48-1 and SZD-48-3.
24.	-	-	-	-	BE-024/85 "JANTAR-2B" concerns SZD-42-2 only.
25.	-	-	-	-	BE-025/85 "JANTAR Std 3" concerns SZD-48-3 only.
26.	-	-	-	-	BE-026/86 "JANTAR Std" concerns: SZD-41, SZD-41A, SZD-48-1 and SZD-48-3.
27.	BE-027/86 "JANTAR"	Below listed glider types: SZD-38A, SZD-41A, SZD-42- 1, SZD-42-2, SZD-48, SZD- 48-1 and SZD-48-3 (does not concern SZD-37 (X-105)).	Extension of life-time for cables with metal core for rudder control system of Jantar gliders	The Bulletin is obligatory from the date of issue (receipt).	
28.	BE-028/87 "JANTAR 1"	The gliders SZD-38 and SZD- 38A "JANTAR 1" of Fact. Nos: X-108, X-109 and from B-608 to B-689.	Life-time of SZD-38A "Jantar 1" sailplanes	Obligatory when 1500 flying hours have been completed.	

Pos.	Bulletin No	Ref. to Fact. Nos	Contents of Bulletin	Way of introducing	Remarks
29.	BE-029/87 "JANTAR"	Below listed glider types: <u>SZD-37x, SZD-37, SZD-38,</u> <u>SZD-38A, SZD-41, SZD-41A,</u> <u>SZD-41B, SZD-48, SZD-48-1</u> and SZD-48-3.	Additional securing of the bolt connecting the tailplane with the fin against the automatic disconnection.	Acc. to user's decision.	
30.	-	-	-	-	BE-030/87 "JANTAR-2B" concerns SZD-42-2 only.
31.	-	-	-	-	BE-031/87 "JANTAR-2" concerns SZD-42, SZD-42-1 and SZD-42-2.
32.	BR-032/87 "JANTAR"	Below listed glider types: <u>SZD-37x, SZD-37, SZD-38,</u> <u>SZD-38A, SZD-41, SZD-41A,</u> <u>SZD-42, 42-1, SZD-42-2,</u> <u>SZD-48, SZD-48-1, SZD-48-3</u> and SZD-48-3M.	Compensation of plays in wing-to-fuselage connection /or middle wing-to-wingtip/ of Jantar sailplanes family.	In case the "excessive" plays appear, as defined in the Bulletin, obligatory to be introduced.	
33.	-	-	-	-	BE-033/88 "JANTAR Std 2" concerns: SZD-48 and SZD-48-1.
34.	-	-	-	-	BE-034/88 "JANTAR Std" concerns: SZD-41, SZD-41-1 (SZD-41A), and SZD-41B.
35.	-	-	-	-	BE-035/88 "JANTAR Std 3" concerns SZD-48-3 only.
36.	BE-036/89 "JANTAR-1"	SZD-38A gliders of Fact. Nos: B-617, B-673, B-687 and B-688 or the others on which the bolts are replaced acc. to the Bulletin BE-028/87 "JANTAR 1"	Extension of the life-time up to 4500 flying hours for the SZD-38A "Jantar 1" sailplanes on which the spar root pins have been replaced acc. to the BE-028/87 "Jantar 1"	Acc. to user's decision.	

Pos.	Bulletin No	Ref. to Fact. Nos	Contents of Bulletin	Way of introducing	Remarks
37.	-	-	-	-	BE-037/89 "JANTAR Std" concerns: 1) SZD-41A (except of B-700 to B-703) 2) SZD-48 and SZD-48-1 (except of B-1266 and B-1268.
38.	-	-	-	-	BR-038/89 "JANTAR 2B" concerns SZD-42-2 only.
39.	-	-	-	-	BE-039/89 "JANTAR 2" concerns: SZD-42-1 and SZD-42-2.
40.	BE-040/90 "JANTAR"	Below listed glider types: SZD-38A, SZD-41A, SZD-42-1, SZD-42-2, SZD-48, SZD-48-1 and SZD-48-3.	Replacement of the driving pin of the claw-coupling body in the automatic control system connection of the Jantar family gliders.	Acc. to user's decision.	
41.	BI-041/90 "JANTAR"	All types of "JANTAR" family gliders.	Actualization of "List of Bulletins issued up to date for Jantar family gliders' (status on 31 May 1990)	To be dealt as the information.	
42.	-	-	-	-	BE-042/92 "JANTAR Std 3" concerns SZD-48-3 only.
43.	-	-	-	-	BE-043/92 "JANTAR" concerns SZD-48-1, SZD-48-3 and SZD-42-2 type.
44.	-	-	-	-	BE-044/93 "JANTAR Std" concerns SZD-41, SZD-41A and SZD-41B types.

Pos.	Bulletin No	Ref. to Fact. Nos	Contents of Bulletin	Way of introducing	Remarks
45.	BE-045/93 "JANTAR"	All Jantar gliders: SZD-37x, SZD-38, SZD-38A, SZD-42, 42-1, 42-2, SZD-48, 48-1, 48-3 SZD-41, 41A, 41B, 41-1.	Cancellation of every 6 years inspection for all types of Jantar and Jantar Standard gliders.	Obligatory when this Bulletin is received.	
46.	-	-	-	-	BE-046/95 "JANTAR" concerns SZD-42, SZD-42-1 and SZD-42-2 type
47.	-	-	-	-	NOT ISSUED
48.	-	-	-	-	BE-048/96 "JANTAR Std" concerns SZD-48, SZD-48-1, SZD-48-3 type