

**LIST OF BULLETINS ISSUED UP TO DATE FOR SZD-42, SZD-42-1 and SZD-42-2 GLIDERS**

Pos.	Bulletin No	Ref. to Fact. Nos	Contents of Bulletin	Way of introducing	Remarks
1.	BE-01/77 SZD-42-1 "JANTAR-2"	Gliders of following fact. numbers: X-126, B-776 to B-781.	Extension of the flight limitations.		
2.	BE-02/78 SZD-42-2 "JANTAR-2B"	Gliders of following fact. numbers: X-131, B-858 to B-866 and B-868 to B-870.	Extension of the flight limitations.		
3.	BE-03/79 SZD-42-2 "JANTAR-2B"	Gliders of following fact. numbers: X-131, B-858 to B-866 and B-868 to B-870.	Replacement of page in Technical Service Manual.		
4.	BE-04/79 SZD-42-2 "JANTAR-2B"	Gliders of following fact. numbers: X-131, B-856 to B-866 and B-868 to B-870.	Change in Flight Manual.		
5.	-	-	-	-	Item used as BE-05/78 "Jantar Std"
6.	-	-	-	-	Item used as BE-06/79 "Jantar Std"
7.	BE-07/80 "JANTAR"	All below mentioned gliders: SZD-37x, SZD-38, SZD-38A, SZD-41, SZD-41A, SZD-41B, <u>SZD-42</u> , <u>SZD-42-1</u> , <u>SZD-42-2</u> , SZD-48 and SZD-48-1.	Lacquer removal from the spar root end, rood end and root rib, then painting with colourless lacquer.	Introduce during nearest pause in flying.	
8.	BE-08/79 "JANTAR"	All gliders: SZD-37x, SZD-38, SZD-38A, <u>SZD-42</u> , <u>SZD-42-1</u> , <u>SZD-42-2</u> .	Change of overhaul life time up to 1500 flying hours and inspections relevant to this.	After completing previous established flying hours of after 6 years of operation.	
9.	BE-09/80 "JANTAR-2B"	Gliders "JANTAR-2B" of fact. numbers mentioned below: X-131, B-658 to B-875, B-908 and B-1065.	Securing of the auxiliary spring for front undercarriage arm retracting against the automatic disconnection of the fuselage frame work hook.	Introduce <u>at once</u> .	
10.	-	-	-	-	Item used as BE-10/80 "Jantar"
11.	-	-	-	-	Item used as BA-011/81 "Jantar"
12.	BK-012/81 "JANTAR-2"	Glider types: SZD-42, 42-1 and 42-2 up to B-1074 incl.	Protection of the polyamide bearing sleeve of the lower rudder mounting against the possibility of its cut-off resulted by groundroughness shocks.	Introduce at once.	
13.	-	-	-	-	Item used as BS-13/81 "Jantar"

Pos.	Bulletin No	Ref. to Fact. Nos	Contents of Bulletin	Way of introducing	Remarks
14.	-	-	-	-	Item used as BK-014/81 "Jantar"
15.	BK-015/81 "JANTAR"	Glider types mentioned below: SZD-37x, SZD-37, SZD-38, SZD-38A, SZD-41, 41A, 41B, <u>SZD-42, 42-1, SZD-42-2</u> up to serial No. B-1126 incl., SZD-48, SZD-48-1 up to serial No. B-1195 incl. and SZD-49.	Securing of the instrument panel cover against the unintentional shifting out of the fixing.	Introduce after receive Bulletin.	
16.	BR-016/81 "JANTAR"	Below listed glider types: SZD-37, SZD-38, SZD-38A, <u>SZD-42, SZD-42-1</u> Fact. Nos X-128, from B-776 to B-792, B-867, B-876, <u>SZD-42-2</u> Fact. Nos X-131, from B-858 to B-866, from B-868 to B-879, B-908, from B-934 to B-953, B-964, from B-1065 to B-1074, from B-1125 to B-1134 and from B-1305 to B-1214; SZD-48 and SZD-48-1.	Replacement of the bolts connecting the aileron control lever in wing with aileron.	The change described in the Bulletin shall be introduced up to 30 Sept. 1983.	
17.	BI-017/82 "JANTAR"	Below listed glider types: SZD-37, SZD-38, SZD-38A, SZD-41, SZD-41A, SZD-41B, <u>SZD-42, SZD-42-1, SZD-42-2,</u> SZD-48 and SZD-48-1.	The list of issued Bulletins for Jantar gliders updated condition on day April 30, 1982	To be dealt as the information.	
18.	BA-018/83 "JANTAR-2B"	Below listed glider types: <u>SZD-42-2</u> Fact. Nos B-1066, from B-1068 to B-1074, from B-1125 to B-1134 and from B-1305 to B-1312.	Inspection of glue joints between the inner wing spar to skin connection in the vicinity of inner to outer wing panels fitting.	The recommendations contained in this Bulletin shall be introduced immediately.	
19.	BK-019/83 "JANTAR"	Below listed glider types: SZD-37x, SZD-38, SZD-38A, SZD-41, SZD-41A, SZD-41B, <u>SZD-42, SZD-42-1, SZD-42-2,</u> SZD-48 and SZD-48-1.	Replacement of compensation volume fastening clamps in the instrument panel.	Bulletin recommended by the producer. The way of introducing is left for the user's decision.	
20.	-	-	-	-	BE-020/83 "Jantar Std 3" concerns: SZD-48-3 only.

Pos.	Bulletin No	Ref. to Fact. Nos	Contents of Bulletin	Way of introducing	Remarks
21.	-	-	-	-	BE-021/84 "JANTAR Std 3" concerns SZD-48-3 only.
22.	-	-	-	-	BE-022/85 "JANTAR Std 3" concerns SZD-48-3 only.
23.	-	-	-	-	BE-023/85 "JANTAR Std" concerns SZD-48, SZD-48-1 and SZD-48-3.
24.	BE-024/85 "JANTAR-2B"	Concerns the SZD-42-2 "Jantar 2B" gliders with factory installed hook or hooks of SZD-III P model, as well as replaced in operation on base of Bulletin BS-03/78 SZD-38A Jantar 1. The statements of this bulletin have been introduced into the glider associated documents for ships from Fact. No B-1486.	Revisions in Technical Description, Technical Service Manual for SZD-42-2 "Jantar 2B" due to the installation of the towing hooks of SZD-III-A-56 type P on some gliders of above model.	Obligatory when this Bulletin is obtained.	
25.	-	-	-	-	BE-025/85 "JANTAR Std 3" concerns SZD-48-3 only.
26.	-	-	-	-	BE-026/86 "JANTAR Std" concerns: SZD-41, SZD-41A, SZD-48-1 and SZD-48-3.
27.	BE-027/86 "JANTAR"	Below listed glider types: SZD-38A, SZD-41A, SZD-42-1, SZD-42-2, SZD-48, SZD-48-1 and SZD-48-3 (does not concern SZD-37 (X-105)).	Extension of life-time for cables with metal core for rudder control system of Jantar gliders	The Bulletin is obligatory from the date of issue (receipt).	
28.	-	-	-	-	BE-028/87 "JANTAR 1" concerns SZD-38A only.

Pos.	Bulletin No	Ref. to Fact. Nos	Contents of Bulletin	Way of introducing	Remarks
29.	-	-	-	-	BE-029/87 "JANTAR" concerns SZD-37, SZD-38, SZD-41, SZD-41A, SZD-41B, SZD-48, SZD-48-1 and SZD- 48-3.
30.	BE-030/87 "JANTAR-2B"	The gliders of <u>SZD-42-2</u> "JANTAR-2B" type of Fact. Nos X-121 and from B-858 to B-1672 incl.	Inspection of fitting the balancing weights in the fuselage nose.	Obligatory when this Bulletin is received.	
31.	BE-031/87 "JANTAR"	Below listed glider types: <u>SZD-42</u> "JANTAR-2" (X-119 and X-120), <u>SZD-42-1</u> "JANTAR-2A" (X-128 and from B-776 to B-867) and <u>SZD-42-2</u> "JANTAR-2B" (from B-858 higher Nos).	Revision of life-time of SZD-42 „Jantar2”, SZD-42-1 „Jantar 2A” and SZD-42-2 „Jantar 2B” sailplanes from 1500 into 3000 flying hours.	Acc. to user's decision.	
32.	BR-032/87 "JANTAR"	Below listed glider types: SZD-37x, SZD-37, SZD-38, SZD-38A, <u>SZD-41</u> , SZD-41A, <u>SZD-42</u> , <u>SZD-42-1</u> , <u>SZD-42-2</u> , SZD-48, SZD-48-1, SZD-48-3 and SZD-48-3M.	Compensation of plays in wing-to-fuselage connection /or middle wing-to-wingtip/ of Jantar sailplanes family.	In case the "excessive" plays appear, as defined in the Bulletin, obligatory to be introduced.	
33.	-	-	-	-	BE-033/88 "JANTAR Std 2" concerns: SZD-48 and SZD-48-1.
34.	-	-	-	-	BE-034/88 "JANTAR Std" concerns: SZD-41, SZD-41-1 (SZD-41A), and SZD-41B.
35.	-	-	-	-	BE-035/88 "JANTAR Std 3" concerns SZD-48-3 only.
36.	-	-	-	-	BE-036/89 "JANTAR-1" concerns SZD-38A only.

Pos.	Bulletin No	Ref. to Fact. Nos	Contents of Bulletin	Way of introducing	Remarks
37.	-	-	-	-	BE-037/89 "JANTAR Std" concerns: 1) SZD-41A (except of B-700 to B-703) 2) SZD-48 and SZD-48-1 (except of B-1266 and B-1268).
38.	BE-038/89 "JANTAR-2B"	Glider types: <u>SZD-42-2</u> "JANTAR-2B" Fact. Nos X-131 and from B-858 to B-1563 (except of B-859).	Complementation of the undercarriage locking in the retracted position.	Acc. to user's decision (as recommendation).	
39.	BE-039/90 "JANTAR"	Glider types: 1) SZD-42-1 "JANTAR-2A" (X-128 and from B-776 to B-792, B-867 and B-876); 2) SZD-42-2 "JANTAR-2B" (X-131 and from B-858 to B-1131).	Inspection for correct assembling of aileron control lever in the wing guides.	In case of disassembling of inner aileron of its shifting-off out of the hinges the inspection is to be carried on immediately.	
40.	BE-040/90 "JANTAR"	Below listed glider types: <u>SZD-38A, SZD-41A, SZD-42-1, SZD-42-2, SZD-48, SZD-48-1 and SZD-48-3.</u>	Replacement of the driving pin of the claw-coupling body in the automatic control system connection of the Jantar family gliders.	Acc. to user's decision.	
41.	BI-041/90 "JANTAR"	All types of "JANTAR" family gliders.	Actualization of "List of Bulletins issued up to date for Jantar family gliders' (status on 31 May 1990)	To be dealt as the information.	
42.	-	-	-	-	BE-042/92 "JANTAR Std 3" concerns SZD-48-3 only.

Pos.	Bulletin No	Ref. to Fact. Nos	Contents of Bulletin	Way of introducing	Remarks
43.	BE-043/92 "JANTAR"	Bulletin covers these sailplanes of "Jantar" family where the ball bearings have been used as the rollers of the push-rod guides, which contact the push-rod (metal on metal). It is used in the sailplanes of SZD-48-1 "Jantar Std 2", SZD-48-3 "Jantar Std 3" and SZD-42-2 "Jantar-2B" type.	Appreciation of wear degree of the push-rod duraluminium tube surface in the location of contact with the ball bearing being used as the guiding rollers in the guides.	As necessary.	
44.	-	-	-	-	BE-044/93 "JANTAR Std" concerns SZD-41, SZD-41A and SZD-41B types.
45.	BE-045/93 "JANTAR"	All Jantar gliders: SZD-37x, SZD-38, SZD-38A, SZD-42, 42-1, 42-2, SZD-48, 48-1, 48-3 SZD-41, 41A, 41B, 41-1.	Cancellation of every 6 years inspection for all types of Jantar and Jantar Standard gliders.	Obligatory when this Bulletin is received.	
46.	BE-046/95 "JANTAR"	All gliders of SZD-42, SZD-42-1 and SZD-42-2 with four panel wings.	Performing the detailed inspection of pin installation in outboard wing spar end.	Immediately after receiving the Bulletin.	
47.	-	-	-	-	NOT ISSUED
48.	Bulletin No BE-007/94 "Cable tension members"	All SZD gliders	Standardization of servicing basic for cable tension members in all SZD gliders	Obligatory when this Bulletin is obtained, to make easier the servicing of gliders	