

1 LIST OF BULLETINS ISSUED UP TO DATE FOR SZD-32A "Foka 5" GLIDER

Actual status: 1st May 2008

Pos.	Bulletin No	Ref. to Fact. Nos	Contents of Bulletin	Way of introducing	Remarks
1.	Bulletin of changes No 61 /1969/	Factory Nos W-419 to W-439	<ol style="list-style-type: none"> 1. Flight Manual 2. Technical Description 3. Assembling of fairing of all moving tailplane fitting 4. Assembling of now bob-weight of tailplane 5. Replacement of connector in tab control system 	In operation	
2.	Bulletin No BR-001/70 "Foka 5"	Factory Nos W-478 to W-498	Improvement of work of pins 67-34-06 and 67-64-11 and nests 71-41-00 and 71-42-00 in the spar of tailplane	Immediately	
3.	Bulletin No BE-002/75 "Foka C", "Foka 4A" „Foka 5”, „Cobra 15"	All gliders /having the wooden ailerons/	Inspection of fitting of aileron bob-weights.	In the nearest inspection after 100 flying hours	Joint Bulletin for SZD-24C, SZD-24-4A, SZD-32A and SZD-36A
4.	Bulletin No /003/	-	-	-	Bulletin No 003 has not been issued
5.	Bulletin No BE-004/72 "Foka 5"	All gliders operated in East Germany	Revision of flight limitations for SZD-32A "Foka 5" gliders operated in East Germany	Acc. to requirements of East Germany	Valid for East Germany only
6.	Bulletin No BE-005/81 "Foka 5"	All SZD-32A "Foka 5" gliders	Change of maintenance works schedule and further operation of SZD-32A "Foka 5" gliders	Acc. to users decision	
7.	Bulletin No BI-006/83 "Foka 5"	All SZD-32A "Foka 5" gliders	List of all Bulletins for SZD-32A "Foka 5" gliders issued till today.	For information only	